



BRP US Inc./Outboard Engines Division
After Sales Support
P.O. Box 597
Sturtevant, WI, USA 53177
T 847.689.7090 F 847.689.6902

www.brp.com

«first» «last»
«address2»
«address»
«city», «st» «zip»

«model » «serial»

EPA RECALL NOTICE

April 23, 2010

RE: 2009 and 2010 Evinrude® E-TEC® 15HP, 25HP, 30HP, 40HP, 55HP and 65HP outboard models, from serial number 5259331 to 5295026 and 8750021 to 8755514 with affected fuel hose and primer bulb assembly part number 177006 or part number 5006365.

Dear *Evinrude E-TEC* Registered Owner:

This notice is sent to you in accordance with the requirements of the U.S Environmental Protection Agency (EPA) and other applicable laws and regulations.

This notice is sent to you because our records indicate that you are the owner of an *Evinrude E-TEC* outboard affected by this recall. Your *Evinrude E-TEC* outboard requires an important service procedure.

What is the reason for this notice?

BRP US Inc. in the United States and Bombardier Recreational Products Inc. in Canada (collectively "BRP") are conducting a voluntary EPA recall on certain *Evinrude E-TEC* 15–65 HP outboard.

What is the problem?

As defined in Title 40 of the Code of Federal Regulations, as a manufacturer, BRP is required to correct engines that may be emitting pollutants in excess of Federal emission standards. An incorrect fuel hose type contained in the fuel hose and primer bulb assembly may have been provided with the engine. This fuel hose type will emit fuel vapors that have been shown to harm the environment. This issue can be corrected by replacing the fuel hose and primer bulb assembly on the above listed outboard models.

Please note that if the engine is not serviced to correct this issue, it may fail a state or local emission test.

What should you do?

Contact an authorized *Evinrude/Johnson* dealer and make an appointment to have the fuel hose and primer bulb assembly inspected or replaced. This service will be performed at no charge. Transportation of the boat to the dealer and related hauling expenses are the responsibility of the owners.

What to do if you feel this notice is in error.

This notice was mailed to you according to the most current information we have available. Affected *Evinrude E-TEC* outboard(s) **must** be serviced. If you no longer own your *Evinrude E-TEC* outboard, kindly complete and return the enclosed postage-paid reply card, so we may update our records and contact the current owner about this important EPA recall.

Need assistance locating an authorized dealer?

To contact the nearest authorized *Evinrude/Johnson* dealer, use the dealer locator on our web sites at www.evinrude.com, or www.johnson.com. You may also contact us via phone at 847-689-7090.

We apologize for any inconvenience that this recall may cause you.

BRP US Inc.